



PAT MCCRORY
Governor

DONALD R. VAN DER VAART
Secretary

MICHAEL SCOTT
Acting Director

March 4, 2016

Mr. McKenzie Mallary
Remedial Project Manager
Superfund Remedial & Site Evaluation Branch
U. S. Environmental Protection Agency, Region 4
Sam Nunn - Atlanta Federal Center
61 Forsyth Street, S.W.
Atlanta, GA 30303

RE: Upland Soil Non-Time Critical Removal Action – 2015 Monitoring Report
Estech General Chemicals Site
Navassa, Brunswick County, North Carolina
NCD 051 827 905

Dear Mr. Mallary:

The North Carolina Department of Environmental Quality (NC DEQ) Division of Waste Management (DWM) Superfund Section has received the *Upland Soil Non-Time Critical Removal Action – 2015 Monitoring Report* for the Estech General Chemicals Site located in Navassa, North Carolina. The NC DEQ DWM Superfund Section has reviewed this document and offers the following attached comments.

The NC DEQ DWM Superfund Section appreciates the opportunity to comment on this document. If you have any questions or comments, please feel free to contact me at (919) 707-8336 or at david.mattison@ncdenr.gov.

Sincerely,

A handwritten signature in black ink that reads 'David B. Mattison'.

David B. Mattison
Environmental Engineer

Federal Remediation Branch
Superfund Section
Division of Waste Management
North Carolina Department of Environmental Quality

Attachment

Upland Soil Non-Time Critical Removal Action – 2015 Monitoring Report Estech General Chemicals Site

Attachment A Photographs and Soil NTCRA Components 2015 Inspection Forms

1. There are two photographs identified as Photo No. 4427 in Appendix A – *Photographs and Soil NTCRA Components 2015 Inspection Forms*. It appears from the Inspection Forms submitted in Appendix A that the second photograph identified as Photo No. 4427 is actually Photo No. 4429. Please clarify this discrepancy.

2. Photo No. 4437 and Photo No. 4436 included in Appendix A – *Photographs and Soil NTCRA Components 2015 Inspection Forms* indicate that the photographs are taken facing the west. However, the Inspection Forms submitted in Appendix A indicate that Photo No. 4437 and Photo No. 4436 are taken facing the east. Please clarify these discrepancies.